




Visit us: www.costway.com


Board Identification



COSTWAY

www.costway.com


COSTWAY www.costway.com



Board Identification

Not actual size

www.costway.com



 4×13 4pcs

Holder Screws

-11111

 8×40 4pcs

Expansion Tube

 4×40 19pcs

Board Screws

 6×20 lpcs

Dowel

www.costway.com

6×60 2pcs

Cup Holder

 3×20 l6pcs

Rack Screws

*mmmmm>


 6×60 4pcs

Wall Screws

 340×110 2pcs Cup Holder

PRODUCT ASSEMBLY


STEP 2



Assemble A1 to D, then fix C on the top of A1

COSTWAY

www.costway.com



 6×60 4pcs


Wall Screws

 8×40 4pcs

Expansion Tube

 4×13 4pcs

Holder Screws



Cutting

Counterbore

Cutting

PRODUCT ASSEMBLY

STEP 13

Insert 5 to 4, and 5 to 6 seperately (counterbore


side outside)

Insert 3 as above

COSTWAY

www.costway.com

STEP 3



Insert 5 to 1 and 2 as above. (The top of 3 is

against 4)

PRODUCT ASSEMBLY

Top of 5

Insert 5 to 1 and 2 as above. (The top of 5 is

COSTWAY


www.costway.com

against 1)

Counterbore

Insert 7 and 8 and two pieces of 1seperately. (counterbore side outside)

Maximum Loads



Liquid spills should be removed immediately. Using a soft clean

Check bolts/screws periodically and tighten them if necessary.

Further advice about wood furniture care

It is best to keep your furniture in a climate-controlled environment.

It is advised to keep furniture away from direct sunlight as sun may

Proper care and cleaning at home will extend the life of your purchase.

Following these important and helpful tips will enhance your furniture

_____ 14 _____


Extreme temperature and humidity changes can cause fading,

cloth, blot the spill gently. Avoid rubbing.

warping, shrinking and splitting of wood.

damage the finish.

as it ages.



5 Star Rating

_____ 15 _____

We would like to extend our heartfelt thanks to

all of our customers for taking time to assemble

this product and giving us valuable feedbacks.